






MEYER WISMAR SárI & Co. KG; Wendorfer Weg 5; 23966 Wismar; Germany
 Yard Information and Safety Instructions





  The representative accompanying you is informed about escape routes and locations of rescue equipment. In the event of any emergency his instructions must be followed.


 Please look out for any obstacles in your path. There is a risk of tripping and falling or bumping against something. Marked routes must be followed.


 The production areas of the shipyard should only be entered wearing a helmet, a protective jacket and safety shoes. We recommend the use of protective goggles which are mandatory in some specifically marked areas.


 Emergency assembly points are clearly marked. Their location is shown on the site plan.


 People with pacemakers should keep a sufficient safety distance from electrical devices.


 Do not look directly into welding arcs! Additionally, you should protect your eyes against sparks and other particles, preferably using protective goggles.


 Particular care must be taken in the production areas as heavy loads are transported here. Keep an eye out for cranes and warning signals and stand clear of suspended load.

 Look out for forklift trucks and other traffic in the production areas and on the site. Traffic routes are not always clearly separated.

 Do not use or operate any tools, devices or machinery.

 Taking photos on the company territory is not allowed. Exceptions require a special permit.

 Alcohol and drugs are strictly prohibited.

 There is an absolute smoking ban on ships or other objects.

 There is video surveillance on the site.

- A** Design office
- B** Office building
- C** Office of production planning/control/scheduling
- D** Foremen and headmen
- E** Foremen and headmen
- F** Office building
- G** Meeting Rooms
- 10 Cutting shop
- 11 Profile shop
- 12 Transverse connecting wing
- 15 Plate stock
- 16 Profile stock
- 17 Pipe stock
- 20 Panel shop
- 30 Hull production shop
- 40 Voluminous unit production shop
- 41 Roofed area
- 50 Coating shop
- 60 Dock shop
- 62 Building dock
- 67 Shop 4/welding training centre
- 70 Assembly centre
- 80 Central stock
- 84 Parrot building
- 85 Main stock
- 91 Stock of components
- 93 Reloading site

-  Assembly point
-  Company doctor
-  Company fire brigade